1847 24th Avenue Court
Greeley, CO 80631
October 16, 1985

Mr. Tom Bent
9016 Flicker Place
Columbia, MD 21045

Call

Dear Tom:

Enclosed is a considerably revised version of the article(s), "Evaluation of the Aerco 2068 Disc Interface", which I had sent you earlier. It's no doubt a good thing that you did not publish the earlier version in the Sept-Oct issue of SyncWare News, because of the update kit which Aerco has just begun to ship out. Also, it was certainly appropriate to publish the several contest-winning programs. I presume that you are still interested in the Aerco article for an upcoming issue. The enclosed article is still fairly long, but is what I consider the minimum introductory article on the subject. You might find ways to trim or subdivide it, however.

Also enclosed is a diskette with two files, AercoA and AercoB, which contain this article. These will run on the TasWord program I sent you previously.

I expect to have TasWord updated for the new Aerco ROM (and including a few other improvements) within about two weeks. That, preceded by comments on how to run programs with variable names and addresses, will make up the second proposed article. The Aerco ROM modifications have made possible considerable reductions in the length of that material. Of course, the first version of TasWord AD (after disc) which I sent you stillworks on the updated ROM.

Hope you find this material to be of value.

Sincerely,

Bill Fadner

W. L. Fadner

Send letter to get current update of this article.

See if Tom B has disc?